

August 18, 2015

Re: Ringler Energy, LLC

Class B Biosolids Site Authorization

NPDES

Morrow County 4IN00204*AD

Mr. Bruce Bailey
Vice President of Technical Affairs
quasar energy group
5575 Granger Road, Suite 320
Independence, OH 44131

Dear Mr. Bailey:

Ohio EPA received a request on July 20, 2015, from quasar energy group to include the following sites as part of the Ringler Energy, LLC biosolids management program:

<u>Field ID</u>	Ohio EPA Site #	County	<u>Township</u>
MOQ-11-04	59-00112	Marrow	Westfield
MOQ-11-05	59-00113	Morrow	Lincoln

These sites are owned and operated by Ohio EPA Site 59-00112 is located northwest of the intersection of Westfield-Fulton Road and Showmaker Road. Ohio EPA Site 59-00113 is located north of Waldo-Fulton-Chesterville Road, approximately 0.5 mile east of Reader Road.

A review of these sites was conducted by Ohio EPA. Consideration was given to soil and landscape characteristics, isolation distances from residences, geology and ground water conditions, and the proximity to waterways and wells.

The review indicated that portions of these sites contain hydrologic group D soils. Please refer to the precipitation prohibitions and restrictions for group D soils found in Ohio Administrative Code (OAC) 3745-40-08(B)(2).

These sites are authorized to be included as part of the Ringler Energy, LLC biosolids program. This authorization is subject to conditions contained in both the NPDES permit and OAC 3745-40. Conditions contained in the NPDES permit and OAC 3745-40 may differ. In such cases, the more restrictive conditions from either the NPDES permit or OAC 3745-40 shall govern.

Highlights of these conditions are as follows:

- Biosolids shall not be applied in buffer zones.
- 2. In accordance with federal/state rules, biosolids may not be applied within 33 feet of surface waters of the state.
- 3. Biosolids application shall be timed to avoid periods of excessive wetness to help prevent runoff from a site.

4. Records for the application of biosolids on these sites shall be maintained in accordance with the requirements found in OAC 3745-40-09(C).

All biosolids beneficially used at these sites shall be injected beneath the surface of the ground or immediately incorporated into the soil. Additional isolation distance from surface waters of the state may need to be provided to account for potential runoff and to ensure that the required thirty-three feet isolation distance is maintained. Biosolids that remain on the surface shall be incorporated within six hours.

If you have any questions, please contact me at (614) 644-2150 or via email at betsy vanwormer@epa.ohio.gov.

Sincerely,

Betsy P. L. VanWormer, P.E. Environmental Engineer II

Ohio EPA - Division of Surface Water

Cc: Morrow County Health Department

Morrow County Soil and Water Conservation District

Westfield Township Trustees Lincoln Township Trustees

Ec: Cassie Elbin, quasar energy group

Isaac A. Robinson, III, Chief, Ohio EPA/CDO

Betsy P. L. Van Wormer



Site Authorization Class B Biosolids

Ohio EPA Site 59-00112

Ringler Energy, U.C.

MOQ-11-04

WestfieldTownship Morrow County

Ser HERE DeLorme: Mannwinga © SpenStreetMapscontributors 59-00081 59-00080 59-00112 59-00079 CA S 59-00076 59-00095 59-00072 59-00075 59-00073 59-00097 59-00107 59-00074

Ohio Environmental Protection Agency

Division of Surface Water 50 W Town Street, Suite 700 Columbus, OH 43216 (614) 644-2150



Site Authorization Class B Biosolids

Ringler Energy, LLC

Ohio EPA Site 59-00113

Mog-11-05

Lincoln Township Morrow County

Ohio Environmental Protection Agency

Division of Surface Water 50 W Town Street, Suite 700 Columbus, OH 43216 (614) 644-2150